- D. Certificate: Certify that Products meet or exceed specified requirements.
- E. Manufacturer's Installation Instructions: Indicate special procedures and perimeter conditions requiring special attention.

## 1.6 SUBMITTALS AT PROJECT CLOSEOUT

- A. Section 01700 Contract Closeout: Procedures for submittals.
- B. Warranty: Submit completed manufacturer warranty forms in Owner's name and registered with manufacturer.

### 1.7 QUALITY ASSURANCE

- A. Perform Work in accordance with NRCA Waterproofing Manual.
- B. Waterproofing Manual Manufacturer: Company specializing in waterproofing membrane with minimum five-years experience
- C. Applicator: Company specializing in performing the work of this section with minimum fiveyears documented experience and approved by manufacturer.

### 1.8 ENVIRONMENTAL REQUIREMENTS

A. Maintain ambient temperatures above 40° F for 24 hours before and during application and until liqBit 8tn PRA 3th 135279474(1)3527947(1)352794(1)3527947(1)35279(1)35279(1)35279(1)35279(1)35279(1)3579(1)3579(1)3579(1)3579(1)3579(1)3579(1)3579(1)3579(1)3579(1)3579(1)3579(1)3579(1)357

A. Separation Sheet: Sheet polyethylene, 6-mil thick.

# PART 3 EXECUTION

## 3.1 EXAMINATION

- A. Section 01040 Coordination and Meetings: Verify existing conditions before starting work
- B. Verify substrate surfaces are free of frozen matter, dampness, loose particles, cracks, pits, projections, penetrations or foreign matter detrimental to adhesion or application of waterproofing system.
- C. Verify that substrate surfaces are smooth, free of honeycomb or pitting, and not detrimental to full contact bond of waterproofing materials.
- D. Verify items, which penetrate surfaces receiving waterproofing, are securely installed.

## 3.2 PREPARATION

- A. Protect adjacent surfaces not designated to receive waterproofing.
- B. Clean and prepare surfaces to receive waterproofing in accordance with manufacturer's instructions; vacuum substrate clean.
- C. Do not apply waterproofing to surfaces unacceptable to manufacturer:9451(p)-5.49451(l)3.27578(i)3.27578(c)4.4-
  - D. Stot
    - D e Tf 10.68 0 Td ()T811 123(a)T"o ccating of watecprondim

A. Section 01400 - Quality Control: Field inspection,